

Always chose a compatible or matched overlaminate to ensure mutual weathering and to avoid tunnelling or delaminating. Allow sufficient time (24-48 hours) for the print to fully cure before attempting to overlaminate, and ensure that the media and overlaminate are at room temperature.

For best results use a laminating machine. Metamark Overlaminates are suitable for cold lamination, though it is recommended to apply nominal heat (30°C) to the top roller to minimise 'silvering'. All Metamark overlaminates have a solvent-based adhesive* to ensure trouble free application whether applying wet or dry.

To avoid tunnelling and delamination, roll the materials 'Print side out' and avoid rolling tightly.

*Except MetaGuard MG-100



Bestel direct op SignSeen.nl

info@signseen.nl
+31 (0) 318 502 897

Arkeneel 27
3905 NS
Veenendaal

For further technical support email technical@metamark.co.uk or call +44 (0)1483 571111

Metamark (UK) Limited

Luneside • New Quay Road • Lancaster • LA1 5QP • Tel +44 (0)1524 387140 • Fax +44 (0)1524 387147

Metamark House • Octimum Business Park • Forsyth Road • Woking • GU21 5SF • Tel +44 (0)1483 571111 • Fax +44 (0)1483 570540

sales@metamark.co.uk

www.metamark.co.uk